

# Proposed Changes to Design and Construction Standards Manual Section 700

September 2019

Marc Aveni Environmental Services




Problems encountered by staff through resident complaints:

- 1) Runoff from large drainage areas flowing through single family lots
- 2) Swales (less defined ditches) located too close to homes and home openings (window wells/basement areaways) causing yard and basement flooding
- 3) Inadequate overland relief points to safely and adequately pass stormwater flows




- 5) Approved lot grading plans adversely altered because of builder changes to finished floor/footing elevation as well as other deviations from approved plans
- 6) Swales provided with less than 2 percent slope or nearly flat longitudinal slopes (water does not flow)
- 7) Inadequate positive drainage away from the foundation and nearby home openings













Example of a swale



These issues have resulted in staff proposing minor modifications to the DCSM in response to BOCS initiated amendments to Section 700 on June 25, 2019, as well as many meetings held with industry...

- Restricting maximum overland flow to 2 cfs (cubic feet per second)
   within residential lot sizes ½ ac. or less
- Establishing a minimum setback for a swale from a dwelling to be located at least 15 feet from rear of dwelling and 10 feet from side of dwelling



- For overland relief, staff has proposed a minimum twelve (12) inch
  vertical separation between the overland relief point and the lowest
  opening in a dwelling, such as landings at the top of basement
  areaways (walkup basements), door sills (thresholds) of an entry door
  into the walkout basements, exterior window sills located above
  grade, and top of window wells
- A completed and signed "Builders Lot Grading Inspection Readiness Checklist" provided to the County's inspector prior to issuance of a Certificate of Occupancy





Lack of defined swale directly behind house – note proximity to walk up basement entry





|10|

Lack of defined swale





Lack of defined swale causing yard flooding





Patio about 15 feet from house





|13|





|14|

the required distance




Required lot size	<u>Proposed</u>		Staff Recommendation	
	Rear	Side	Rear	Side
1/2 ac. or less	12*	10*	15*	10*
More than 1/2 ac. but less than 1 ac.	12*	10*	30*	15*
icss than I do.	12	10	30	13
1 ac. or more	12*	10*	30*	20*

\*Centerline of the swale located at the property line if the property line is less than

|15|





|16|





Lack of overland relief led to basement flood






|18|





Drop inlet handling large flows close to basement entrance





Flooded basement



Builders Lot Grading Inspection Readiness Checklist





- If for some reason can not meet these requirements, individual lot waivers are always an option
- Recommend approval of staff recommended setbacks
- Questions or concerns?